

Spill Type	Bleach	Sulfuric Acid	Motor Oil	Hydraulic Fluid
CoirLoc	2.5	2.5	2.5	2.5
Clay	48.44	22.47	29.89	28.91
Spill	21.47	17.67	14.06	13.97
Increased absorbency from clay to CoirLoc	19.37x	8.98x	11.95x	11.56x

CoirLoc vs Clay - amount of absorbent needed to absorb spill by weight in grams

